





HARNESS, DICKEY & PIERCE, P.L.C.

ATTORNEYS AND COUNSELORS
P.O. BOX 828

BLOOMFIELD HILLS, MICHIGAN 48303 U.S.A.

CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY

287637 HARNES UR TELEFACSIMILE (248) 641-0270

May 24, 2004

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450 Certificate

JUN 0 1 2004

of Correction

Re:

U.S. Patent No. 6,718,125

Issued: April 6, 2004

Inventors: Bret S. Clark et al.

For:

BLDC Motor Noise Reduction Using

Constant BUS Current Control Commutation

Sir:

In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

On the Title Page, No. (73), Assignee (Assignment Recorded 12/11/01, Reel 012362, Frame 0090), "Emerson Motor Co." should be --Emerson Electric Co.--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Michael P. Brennan

Reg. No. 30,612

MPB/rc Enclosure



HARNESS, DICKEY & PIERCE, P.L.C.

ATTORNEYS AND COUNSELORS P.O. BOX 828

BLOOMFIELD HILLS, MICHIGAN 48303 U.S.A. CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY
287637 HARNES UR
TELEFACSIMILE

(248) 641-0270

May 24, 2004

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re:

U.S. Patent No. 6,718,125

Issued: April 6, 2004

Inventors: Bret S. Clark et al.

For: BLDC Motor Noise Reduction Using

Constant BUS Current Control Commutation

Sir:

47

In proofreading the above identified application, the following error was noted which appears to require a Certificate of Correction:

On the Title Page, No. (73), Assignee (Assignment Recorded 12/11/01, Reel 012362, Frame 0090), "Emerson Motor Co." should be --Emerson Electric Co.--.

Enclosed herewith is an original and a copy of the Patent and Trademark Office Certificate of Correction form which we request be approved for the above identified patent.

The Director is hereby authorized to charge any additional fees which may be required in connection with this correction to Deposit Account No. 08-0750. A duplicate copy of this letter is enclosed.

Respectfully submitted,

Michael P. Brennan

Reg. No. 30,612

MPB/rc Enclosure Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO:

6,718,125

DATED:

April 6, 2004

INVENTOR(S):

Bret S. Clark et al.

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

On the Title Page,

No. (73), Assignee, "Emerson Motor Co." should be -- Emerson Electric Co.--.

MAILING ADDRESS OF SENDER:

PATENT NO. 6,718,125

Michael P. Brennan, Esq. Harness, Dickey & Pierce, P.L.C. P.O. Box 828

Bloomfield, MI 48303

No. of additional copies

=>

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number. (Also Form PTO-1050)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO:

6,718,125

DATED:

April 6, 2004

Bret S. Clark et al.

INVENTOR(S):

It is certified that error appears in the above-identified patent and that said Letters Patent are hereby corrected as shown below:

On the Title Page,

No. (73), Assignee, "Emerson Motor Co." should be -- Emerson Electric Co.--.

MAILING ADDRESS OF SENDER:

PATENT NO. _ 6,718,125

Michael P. Brennan, Esq. Harness, Dickey & Pierce, P.L.C. P.O. Box 828 Bloomfield, MI 48303

No. of additional copies

=>

Burden Hour Statement: This form is estimated to take 1.0 hour to complete. Time will vary depending upon the needs of the individual case. Any comments on the amount of time you are required to complete this form should be sent to the Chief Information Officer, U.S. Patent and Trademark Office, Washington, DC 20231. DO NOT SEND FEES OR COMPLETED FORMS TO THIS ADDRESS. SEND TO: Assistant Commissioner for Patents, Washington, DC 20231.



HARNESS, DICKEY & PIERCE, P.L.C.

U.S.A.

ATTORNEYS AND COUNSELORS
P.O. BOX 828
BLOOMFIELD HILLS, MICHIGAN 48303

CABLE
PATENTS TROY, MICHIGAN
TELEX NO. & REPLY
287637 HARNES UR
TELEFACSIMILE
(248) 641-0270

May 24, 2004

Director of the U.S. Patent and Trademark Office P. O. Box 1450 Alexandria, VA 22313-1450

Re: Pate

Patent No. 6,718,125

Issued: April 6, 2004

Inventor(s): Bret S. Clark et al.

For:

BLDC Motor Noise Reduction Using

Constant Bus Current Control Commutation

Sir:

We have noted in proofreading Patent No. 6,718,125 the following error:

Column 1, line 36 (application page 2, line 4), after "greater" insert --detail--.

Kindly make this error of record in your files.

Very truly yours,

Michael P. Brennan Reg. No. 30,612

MPB/rc

O/ Paten No. 6,718,125

Attorney Docket No. 3174-000001/CPA

Express Mail Label No. EV 406 075 405 US (5/24/2004)

Certificate of Mailing under 37 CFR 1.8

I hereby certify that this correspondence is being deposited with the United States Postal Service with sufficient postage as express mail in an envelope addressed to:

> Director of the United States Patent and Trademark Office P.O. Box 1450 Alexandria, VA 22313-1450

on May 24, 2004.

Date

Signature

Michael P. Brennan

Typed or printed name of person signing Certificate

Note: Each paper must have its own certificate of mailing, or this certificate must identify each submitted paper.

Submitted herewith is (are):

Certificate of Correction Transmittal (in duplicate)

Certificate of Correction Form PTO/SB/44 (in duplicate)

Errors of Record Letter

Return Postcard